

Document Information

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Vehicles affected:

P13: 540C, 570S, 570S Spider, 570GT, 600LT, 600LT Spider

P14: 720S, 720S Spider

Location: Body Exterior - Wipers and Washer System

Concern: Warning message for washer fluid too low when washer bottle is full

Condition: Permanent

Diagnostic Trouble Codes

N/A

Measure

If customer complaints for the warning message reference washer fluid too low, please do not replace washer bottle as a first point of action.

1. Remove the level sensor from the washer bottle.
2. With a use of a multimeter measure the resistance of the sensor, a good resistance value is 5.7 +/- 2 ohms.
3. If the resistance is correct, re-install the sensor and check if the warning message is still present.
4. If the resistance is incorrect, the washer bottle level sensor is faulty.
5. If the warning message is not present, the issue was that the level sensor was catching on the securing grommet and as a result it wasn't fully home. In this case, replacing the washer bottle assembly will not be covered under warranty.

Attachments



MTI Updates Information

N/A

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.