Document Information

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Vehicles affected: All Models

Location: Powertrain Systems - HVAC

Concern: A/C not cooling followed by Climate System Fault warning message

Condition: Permanent

Diagnostic Trouble Codes

HVAC:

B1A2B27 HVAC: Sensor Evaporator High Rate

B1A2B22 HVAC: Sensor Evaporator O/C

Measure

- 1. Ensure the A/C gas is in the correct level
- 2. Ensure the HVAC module is on the latest / correct software
- 3. Connect the MDS and in HVAC actual values check the Evaporator Temperature value. If equal to $10.0\,^{\circ}$ C, this is the value the HVAC software overwrites on CAN when an evaporator voltage fault occurs
- 4. Access the HVAC module and connector MB152. With the connector still connected measure the voltage between pin 1 and 3 at the back of the MB152 connector. With ambient temperature close to $25\,^{\circ}$ C, the voltage should be around 1.6 V. If it's higher than 4.9V, the HVAC issue could be due to:
- Evaporator sensor harness problem
- Evaporator sensor fault

- 5. To check the harness of the evaporator sensor, follow the steps below:
- 6. Disconnect MB152 of the HVAC module
- 7. Measure the resistance of the evaporator sensor across Pins 1 and 3 Reference values are based on ambient temperature:
- -10° C = 18.46 k ohms +/- 3%
- -15° C = 14.60 k ohms +/- 3%
- -20° C = 11.65 k ohms +/- 3%
- -25° C = 9.34 k ohms +/- 3%
- -30° C = 7.54 k ohms +/- 3%
- 8. Access inline connector IMBIU
- 9. Disconnect IMBIU and check all pins to ensure are tight.
- 10. Then reconnect the IMBIU ensuring is fully engaged. Attempt to clear the fault(s) and check operation of the HVAC (ensure MB152 is re-connected)
- 11. If the original concern is still present proceed to the next step
- 12. If the resistance values at step 7 were correct, repeat the same measurement but this time across Pins 5 and 6 at the inline connector IMBIU. Reference values same as above
- 13. If still measuring open circuit, next step will be to check the evaporator sensor connector. To access this connector the HVAC inlet unit has to be removed.
- 14. If visually all is OK, a new evaporator sensor with it's harness need to be ordered and installed (part number 11A4135CP)

Parts Information

11A4135CP - HVAC Harness

Attachments

Image 1: Location of IMBIU (12C vehicles)





Image 1: Location of IMBIU (Sports Series vehicles)



MTI Updates Information

N/A

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.