


SERVICE CAMPAIGN BULLETIN

TITLE:	Rocker Baffle Foam Upper Removal
CAMPAIGN REFERENCE	045
DOCUMENT NUMBER:	13 A 001
AFFECTED VEHICLES:	Sports Series
SITUATION:	Quality Engineering at McLaren Automotive require the rocker baffle foam upper to be removed due to the possibility of the part becoming detached from the panel in the future.
PROCEDURE:	This rework must be completed on all vehicles when carrying out Pre-Delivery Inspections (PDI) and at the next service centre visit.

Removal:

1. Please refer to CA-RM-02A051-06-001 - Remove/Install rear deck.
2. Proceed and remove the left (1) and right (2) side rocker baffle foam upper.



3. Install the rear deck .

WARRANTY INFORMATION

DESCRIPTION	RESOLUTION CODE	TOTAL REPAIR TIME
Rocker Baffle Foam Upper	CDKA0203A11C2J02	0.20 hours

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY	ORDER PROCESS
NA	NA	NA	NA

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren Bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers. The information contained in McLaren bulletins are for internal use only by McLaren Authorised Retailers and must not be published on external website or social media forums etc.