

## SERVICE CAMPAIGN BULLETIN

TITLE:	Door Latch Replacement
CAMPAIGN REFERENCE:	048
DOCUMENT NUMBER:	13 A 008
AFFECTED VEHICLES:	Sports Series
SITUATION:	Quality Engineering at McLaren Automotive require both door latches to be replaced due to intermittent door latch failure which could result in a customer complaint.
PROCEDURE:	This rework must be completed on all vehicles at PDI or before the handover of a new vehicle to a customer.

## **Removal**

Procedure for McLaren 570S and 540C

1. Please refer to CA-RM-02A052-07-001 - Remove/Install latch and emergency release cable - Door.

Procedure for McLaren 570GT

2. Please refer to CE-RM-02A052-07-001 - Remove/Install latch and emergency release cable - Door - GT.
3. Install the components in reverse order.

Please contact your Regional Aftersales Manager should you have any questions relating to the information contained in this bulletin.

## WARRANTY INFORMATION

DESCRIPTION	RESOLUTION CODE	TOTAL REPAIR TIME
Replace both door latches	CBAF0703A33B4E01	4.35 hours

## PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY	ORDER PROCESS
LH SCL door latch	11A8742CP	1	Unipart
RH SCL door latch	11A8743CP	1	Unipart

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren Bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers. The information contained in McLaren bulletins are for internal use only by McLaren Authorised Retailers and must not be published on external website or social media forums etc.