

McLaren 570S & 600LT – Fuel Hose Replacement; Fuel Tank to Engine

Bulletin type:	Service Campaign
Reference number:	SCB 13 K 001
Attention:	Retailer Service Managers and Retailer Technicians
Affected vehicles:	McLaren 570S and 600LT Coupe and Spider
Situation:	Fuel Hoses require replacement
Procedure:	To action affected vehicles during PDI or Prior to Sale / Handover. Please refer to the information outlined in this document to ensure replacement of the required fuel hoses is carried out
Date:	30 th January 2020

This Service Campaign Bulletin will cover:

1. Overview
2. Procedure
3. Parts Information
4. Warranty Information
5. Affected Vehicles


1. Overview

Through continuous product quality monitoring, it has been identified that a number of McLaren 570S and 600LT vehicles (Coupe and Spider versions) require two fuel hoses to be replaced during PDI or prior to sale/handover of the vehicle.

2. Procedure

To carry out the required re-work, replace the specified fuel hoses.

Document SCB 13 K 001 WI (attached with this Bulletin) contains the relevant work instructions and care points to ensure the repair is carried out correctly, bringing the vehicle up to the current manufacturing standard.



Layout overview – Fuel hoses to be replaced (1)
(extract from SCB 13 K 001 WI)

3. Parts Information

The parts below are required to action this repair, which can be ordered via Unipart.

Part Number	Part Description	Quantity Required
13K0026CP	Fuel feed - Fuel tank	1
13K0027CP	Fuel feed - Engine bay	1

4. Warranty Information

Submit a claim to the McLaren Warranty department following completion of the work, using the following details.

Description	Repair Time
Install Fuel hoses	2.10 hours

5. Affected Vehicles

Your Regional Aftersales Manager will contact you with a list of affected vehicles.

If you have any questions, please speak to your Regional Aftersales Manager.

Best regards,

The information contained in McLaren bulletins is for internal use only by McLaren Authorised Retailers and must not be published on external websites or social media forums etc.

Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.